State of Texas Submitted Drillers Reports Database (SDR):

a cooperative database between the Texas Department of Licensing and Regulation (TDLR) & the Texas Water Development Board (TWDB)

Bryan Anderson Groundwater Data Team Lead Texas Water Development Board





www.twdb.texas.gov 🗗 www.facebook.com/twdboard 🈏 @twdb

Background

- Well Reports & Plugging Reports
 Chapter 1901.251
- Began data collection in 2001, fully implemented in 2003
- Well Reports previous to 2003 available at the Texas Commission on Environmental Quality (TCEQ) Water Well Map Viewer



Development Board

TDLR Statutes and Rules

- WATER WELL DRILLERS/PUMP INSTALLERS
 - Occupations Code Title 12. Practices and Trades
 Related to Water, Health, and Safety Chapter 1901
 & 1902
 - 16 Texas Administrative Code, Chapter 76
 Administrative Rules



Development Board

www.twdb.texas.gov f www.facebook.com/twdboard 🈏 @twdb

Data Required by Statute

The well log shall be recorded at the time of drilling, deepening, or otherwise altering the well and must contain:

- 1. the depth, thickness, and character of the strata penetrated;
- 2. the location of water-bearing strata;
- 3. the depth, size, and character of casing installed; and
- 4. any other information required by rules adopted by the commission.



www.twdb.texas.gov 📕 www.facebook.com/twdboard 🈏 @twdb

Software Platforms

- Microsoft SQL Server 2012
- Texas Well Report Submission and Retrieval System (TWRSRS)
 - Sencha
- Dissemination:
 - SQL Server Reporting Services
 - SQL Server Integration Services
 - ESRI Mapping



Development Board

Integration

- Several databases can reference SDR wells:
 - USGS Groundwater Information System
 - TWDB Groundwater Database*
 - TWDB Brackish Resources Aquifer Characterization System (BRACS)
 - TCEQ Public Water Supply Database
 - Groundwater Conservation District (GCD) databases
 - Owner/Cooperator databases

*links to other databases





Challenges

- Time and resources for development and maintenance
- Several agencies interact with the data
- Organization of dissemination tools
- Identifying the same wells across several databases
- Data entry application security
- Backlog of submitted paper forms






www.twdb.texas.gov 📑 www.facebook.com/twdboard 🈏 @twdb

SDR Reports and Downloads

http://www.twdb.texas.gov/groundwater/data/drillersdb.asp







www.twdb.texas.gov 📘 f www.facebook.com/twdboard 🈏 🖲 twdb

← → // http://www2.t	wdb.texas.gov/ReportServerExt/Pages/	ReportViewer.aspx?%2fSDR%2fWellRj	Q - C Groundwater Dat	Groundwater Dat		
					Weinpagnaria	
Drilling Date Range: From	1	NULL Drilling Date Range	: To			View Report
Owner Name		Well Address				
County	Aransas] Well City				
Well Zip		License Number				
Driller Name] Drilling Company				
Grid Number		Proposed Use	Domestic			
Well Report Tracking Numbe	r]				
14 4 1 of 23 ▶	100%	Find Next 🔍 🗸 😨 🔮				

Submitted Drillers Reports - Well Reports

Drilling 🗘 Well Type Of Composed C Well Address Latitude 🗧 Longitude 🛢 Grid ♦ Drilling ♦ Borehole 🗘 Driller Drilling € Lic DD DD Report Tracking Work Use Name Number Start End Depth (ft.) Name Nu Company Date Date Number 623 Rabbit Run 438549 New Well Domestic Tammy Aransas 27.9450000 -97.1369440 83-07-6 12/6/2016 12/7/2016 182 Michael Mikes Drilling Hickman Road, Aransas Roy Deyo and Pump Pass, 78336 Service 438275 New Well Domestic Arthur Aransas 1002 W Corpus 28.0155560 -97.0744440 79-64-8 12/1/2016 12/2/2016 158 Michael Mikes Drilling Barragan Christi St, Roy Deyo and Pump Rockport, 78382 Service 11/17/2016 11/21/2016 Mikes Drilling 437601 New Well Domestic Dana Wilson Aransas 489 Bee Rd, 27.9888890 -97.1211110 83-08-1 176 Michael Rockport, 78382 and Pump Roy Deyo Service CARTER 436153 New Well Domestic Bill McCall Aransas 2191 Mundine Rd, 27.9673330 -97.1325560 83-07-3 9/29/2016 9/29/2016 150 Scott D WATER Aransas Pass Carter WELL DRILLING 436119 New Well Domestic Chris Aransas 1941 A1 Hil Rd, 27.9619440 -97.1302780 83-07-3 10/26/2016 10/28/2016 187 Michael Mikes Drilling Aransas Pass, Anderson Roy Deyo and Pump Boat Lodge 78336 Service 436098 New Well Domestic James Elder Aransas 1602 W 4th St., 28.0123610 -97.0821670 79-64-8 9/28/2016 9/28/2016 180 Scott D CARTER Rockport Carter WATER WELL DRILLING 436095 New Well Domestic 23 Ospry Dr, 28.1093330 -97.0431390 79-64-2 9/23/2016 9/23/2016 200 Scott D CARTER Dias Aransas Rockport WATER Construction Carter WELL Company DRILLING 436063 New Well Domestic Daniel Aransas 1218 W Moore 27.9325000 -97.1425000 83-07-6 10/25/2016 10/27/2016 168 Michael Mikes Drilling Phillips Ave, Aransas Roy Deyo and Pump Pass, 78336 Service 234 Coastal 180 Scott D CARTER 435955 New Well Domestic Sim Henry 27.9851670 -97.1038330 83-08-1 9/12/2016 9/12/2016 Aransas Wildwood Dr., Carter WATER Rockport WELL




www.twdb.texas.gov f www.facebook.com/twdboard 🈏 @twdb

Development Board

Texas Water

Water Data Interactive


http://www.twdb.texas.gov/mapping/index.asp





Texas Water Development Board


www.twdb.texas.gov 📑 www.facebook.com/twdboard 🈏 @twdb





tdlr Texas Water **Development Board**

www.twdb.texas.gov 手 www.facebook.com/twdboard 🈏 @twdb





Texas Water Development Board

www.twdb.texas.gov f www.facebook.com/twdboard 🈏 @twdb

Questions & Feedback

David Gunn Texas Department of Licensing and Regulation <u>david.gunn@tdlr.texas.gov</u> (512) 334-5539

Bryan Anderson Texas Water Development Board bryan.anderson@twdb.texas.gov (512) 475-3302



Texas Water Development Board

www.twdb.texas.gov 📑 www.facebook.com/twdboard 🈏 @twdb